MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

	SECTION I	
MANUFACTURER'S NAME 3M COMPANY		EMERGENCY TELEPHONE NO. (612) 733-1110
ADDRESS (Number, Street, City, State, and ZIP Code) 3M CENTER, ST. PAUL, MINNESC	TA 55101	
CHEMICAL NAME AND SYNONYMS		TRADE NAME AND SYNONYMS SCOTCHWELD Brand Structural Adhesi
CHEMICAL FAMILY	FORMUL	2214. Regular

SECTION	NII -	HAZAF	RDOUS INGREDIENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL	<u> </u>	,
CATALYST			ALLOYS	ļ	
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX	_	
ADDITIVES			OTHERS	ļ	
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES			%	TLV (Units)	
Resin - bisphenol A type (SPI Class 4)			40	none	
Polyglycol diepoxide resin (SPI Class 2) ~			4	none	
Phenyl glycidyl ether (PGE) ∿		1	10ppm		
			•		

SECT	ION III - F	PHYSICAL DATA	·
BOILING POINT (°F.) Contains no solver	t N.A.	SPECIFIC GRAVITY (H2O=1)	1.44
VAPOR PRESSURE (mm Hg.)	N.A.	PERCENT, VOLATILE BY VOLUME (%) CONTAINS NO SOLVENT	or water
VAPOR DENSITY (AIR=1)	N.A.	EVAPORATION RATE (=1)	N.A.
SOLUBILITY IN WATER essentia	lly nil		<u> </u>
APPEARANCE AND ODOR Gray vis	scous past	ee	

The state of the s			
SECTION IV - FIRE AND EX	XPLOSION HAZARD DATA		
	, 	1 -1	Uel
FLASH POINT (Method used)	FLAMMABLE LIMITS	Lei	Oei -
FLASH POINT (Method used) Contains no flammable liquids - N.A.	N.A		l
EXTINGUISHING MEDIACO, foam, dry chemicals			
CO ₂ , foam, dry chemicals			
SPECIAL FIRE FIGHTING PROCEDURES			
None			
110110			
			•
unusual fire and explosion hazards None known.			
None known.			

SCOTCHWELD Brand Structural Adhesive 2214, Reg.

SECTION V HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE See Section II.
May be irritating to skin. May cause sensitization in some individuals.
EYE Contact: Flush eyes with plenty of water. Call a physician.
SKIN Contact: Wash thoroughly with soap and water. Rinse with water.

		02011	C,	REACTIVITY DATA
STABILITY	UNSTABLE	χ		NS TO AVOID re to temperatures above room temperature
	STABLE		for pr	olonged periods of time.
INCOMPATABILITY Strong oxidi	<i>((Materials to avoid)</i> zing agents.			
CO, CO2, ald	omposition propiety de and oth	ость er orga	nics.	
HAZARDOUS		MAY OCCUR		conditions to Avoid Elevated storage temperatures.
POLYMERIZATION		WILL NOT OCCUR		

SECTION VII SPILL OR LEAK PROCEDURES				
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Scrape up material before resin cures. Place in a container and hold for disposal.				
WASTE DISPOSAL METHOD Incinerate properly in accordance with local regulations. Do not landfill.				

	SECTION VIII - SPECIA	L PROTECTION IN	FORMATION	
RESPIRATORY P	ROTECTION (Specify Type)			
VENTILATION	LOCAL EXHAUST Curing ovens must be ven	ted to the outdoo	SPECIAL DTS.	
	MECHANICAL (General) Acceptab	ole	OTHER	
PROTECTIVE GLOVES Impervious gloves		EYE PROTECTION	EYE PROTECTION Safety glasses	
OTHER PROTECT	IVE EQUIPMENT			

SECTION IX - SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store at 40 F or lower. Allow to return to room temperature before opening. Do
not heat. Avoid eye and skin contact. Avoid breathing fumes during curing.
OTHER PRECAUTIONS Launder contaminated clothing before reuse.